

Таблица замен аналогов реле

Заменяемое реле	Реле ООО «Реон-Техно»
PT 40/0,2	PCT- 40M-0,2
PT 40/0,6	PCT-40M-0,6
PT 40/2	PCT-40M-02
PT 40/6	PCT-40M-06
PT 40/10	PCT-40M-10
PT 40/20	PCT-40M-20
PT 40/50	PCT-40M-50
PT 40/100	PCT-40M-100
PT 40/200	PCT-40M-200
PT 140/0,2	PCT-140M-0,2,
PT 140/0,6	PCT-40-0,6, PCT-140M-0,6
PT 140/2	PCT-40-02, PCT-140M-02
PT 140/6	PCT-40-06, PCT-140M-06
PT 140/10	PCT-40-10, PCT-140M-10
PT 140/20	PCT-40-20, PCT-140M-20
PT 140/50	PCT-40-50, PCT-140M-50
PT 140/100	PCT-40-100, PCT-140M-100
PT 140/200	PCT-40-200, PCT-140M-200
PCT11-09, PCT13-09, PCT11M-09	PCT-40-0,6
PCT11-14, PCT13-14, PCT11M-14	PCT-40-02
PCT11-19, PCT13-19, PCT11M-19	PCT-40-06
PCT11-24, PCT13-24, PCT11M-24	PCT-40-20
PCT11-29, PCT13-29, PCT11M-29	PCT-40-60
PCT11-32, PCT13-32, PCT11M-32	PCT-40-100
PT-81/2, PT-82/2, PT-83/2, PT-84/2, PT-91/2	PCT-80AB-06
PT-81/2, PT-82/2, PT-83/2, PT-84/2, PT-91/2	PCT-80AB-10
PT-81/1, PT-82/1, PT-83/1, PT-84/1, PT-91/1	
PT-81/1, PT-82/1, PT-83/1, PT-84/1, PT-91/1	PCT-80AB-20
PT-81/2, PT-82/2, PT-83/2, PT-84/2, PT-91/2	PCT-82Д-10
PT-81/1, PT-82/1, PT-83/1, PT-84/1, PT-91/1	PCT-82Д-10
PT3-51, PT3-51.01	PCT-51
PCT-11, PCT-11M, PCT-13	PCT-110
PCT40-3-09	PCT-40M-0,6
PCT40-3-14	PCT-40M-02
PCT40-3-19	PCT-40M-06
PCT40-3-21	PCT-40M-10
PCT40-3-24	PCT-40M-20
PCT40-3-26	PCT-40M-50
PCT40-3-31	PCT-40M-100
PCT40-3-34	PCT-40M-200
PCT40-1-09	PCT-40M-0,6
PCT40-1-14	PCT-40M-02
PCT40-1-19	PCT-40M-06
PCT40-1-21	PCT-40M-10
PCT40-1-24	PCT-40M-20
PCT40-1-26	PCT-40M-50
PCT40-1-31	PCT-40M-100
PCT40-1-34	PCT-40M-200
PCT40-1B-09	PCT-40B-0,6
PCT40-1B-14	PCT-40B-02
PCT40-1B-19	PCT-40B-06
PCT40-1B-21	PCT-40B-10
PCT40-1B-24	PCT-40B-20
PCT40-1B-26	PCT-40B-50
PCT40-1B-31	PCT-40B-100
PCT40-1B-34	PCT-40B-200

Заменяемое реле	Реле ООО «Реон-Техно»
PCT40-1B-09	PCT-41B-0,6
PCT40-1B-14	PCT-41B-02
PCT40-1B-19	PCT-41B-06
PCT40-1B-21	PCT-41B-10
PCT40-1B-24	PCT-41B-20
PCT40-1B-26	PCT-41B-50
PCT40-1B-31	PCT-41B-100
PCT40-1B-34	PCT-41B-200
PCT40-2-09	PCT-42-0,6
PCT40-2-14	PCT-42-02
PCT40-2-19	PCT-42-06
PCT40-2-21	PCT-42-10
PCT40-2-24	PCT-42-20
PCT40-2-26	PCT-42-50
PCT40-2-31	PCT-42-100
PCT40-2-34	PCT-42-200
PC-40M-0,5/4	PCT-40M-02
PC-40M-1/8	PCT-40M-06
PC-40M-1/8	PCT-40M-10
PC-40M-5/40	PCT-40M-20
PC-40M-15/120	PCT-40M-50
PC-40M-15/120	PCT-40M-100
PC-40M1-0,5/4	PCT-40B-02
PC-40M1-1/8	PCT-40B-06
PC-40M1-1/8	PCT-40B-10
PC-40M1-5/40	PCT-40B-20
PC-40M1-15/120	PCT-40B-50
PC-40M1-15/120	PCT-40B-100
PC-40M2-0,5/4	PCT-42-02
PC-40M2-1/8	PCT-42-06
PC-40M2-1/8	PCT-42-10
PC-40M2-5/40	PCT-42-20
PC-40M2-15/120	PCT-42-50
PC-40M2-15/120	PCT-42-100
PC-40M21-0,5/4	PCT-42B-02
PC-40M21-1/8	PCT-42B-06
PC-40M21-1/8	PCT-42B-10
PC-40M21-5/40	PCT-42B-20
PC-40M21-15/120	PCT-42B-50
PC-40M21-15/120	PCT-42B-100
PC-80M2-11, PC-80M2-11i	PCT-82ДУ-XX-3, PCT-42ВДУ-XX-3, PCT-82Д-XX-3, PCT-42ВД-XX-3
PC-80M2-15	PCT-82AB-XX-2
PC-80M2-2, PC-80M2-6	PCT-82AB-XX-2
PC-80M2-4, PC-80M2-8	PCT-82AB-XX-1
ППБ-11, ППБ2, УПП, ПБ-1	ППБР-1
ППБ-21, ППБ-22, УПП, ПБ-2, ПБ-3	ППБР-2
МЭР М237	PC-237M